SAMPLE PROVIDER DOCUMENT — NOT AN OFFICIAL FORM

Sample Report — Fictional Property and Findings

Example Pest Services LLC (fictional provider)
Inspector: Riley Chen (fictional) · License: SAMPLE-0000

Visible evidence: mud tubes at rear basement sill plate.
Visible damage: limited surface damage at sill plate (approx. 2 ft).
Conducive conditions: wood-to-soil contact at rear deck post.

Generic sample for demonstration; not a regulatory or insurer form.